CHECKLIST FOR N

BEFORE STARTING

- 1. WALK AROUND INSPECTION
- 2. CHECK FUEL AND CAP
- 3. CHECK OIL
- 4. CHOCK NOSE GEAR 1" WOOD BLOCK

STARTING

- **1. FUEL VALVE ON**
- 2. MIXTURE RICH
- 3. CARB HEAT OFF
- 4. MAGS OFF
- 5. PRIME 3 TIMES
- 6. STAND BETW. WING AND PROP 4 BLADES
- 7. MAGS ON BOTH
- 8. THROTTLE CRACKED

9. START - OIL PRESS. IN GREEN W/IN 30 SEC.

Oil press. @ min. idle 10; norm. run-up 30 to 35 PSI

BEFORE TAKE-OFF

- 1. RUN-UP AT 1800 RPM
- 2. CHECK MAGUS MAX MAG DROP = 125 RPM
- 3. CHECK CARB HEAT
- 4. CHECK INSTRUMENTS AND RADIO
- 5. CHECK CONTROLS
- 6. TRIM NEUTRAL

BEFORE LANDING

- 1. MIXTURE RICH
- 2. CARB HEAT ON
- 3. GEAR DOWN
- 4. FLAPS BELOW 95 MPH
- 5. APPROACH AT 60 MPH

AIRCRAFT SHUTDOWN

- 1. RADIO OFF
- 2. VSI OFF
- 3. PULL MIXTURE FULL LEAN
- 4. MAGUS OFF
- **5. RADIO MASTER OFF**
- 6. FUEL VALVE OFF